

OWNER: PRIESTER AVIATION, LLC
ADDRESS: C/O MAINTENANCE CONTROL
 WHEELING IL 60090
PHONE: 847-850-5444
FAX: 847-537-1133

OPERATOR: PRIESTER AVIATION, LLC
ADDRESS: C/O MAINTENANCE CONTROL
 WHEELING IL 60090
PHONE: 847-850-5444
FAX: 847-537-1133

ANALYST: DAVID VALENCIA
EMAIL: DVALENCIA@CAMPSYSTEMS.COM

+1-631-619-4509 (DIRECT)
 877-411-CAMP (2267) (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 1286/N286NW **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 27-DEC-2011	2654.9 A/C HRS	as of 07-APR-2020	_____ A/C HRS	as of ____/____/____
	1902 AFL	as of 07-APR-2020	_____ AFL	as of ____/____/____
	1345 ACH	as of 22-MAR-2020	_____ ACH	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: PCE-RY0296/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 31-MAY-2011	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS 0 A/C HRS	2654.9 ENG. HRS	as of 07-APR-2020	_____ ENG. HRS	as of ____/____/____
0 ENC	1902 ENC	as of 07-APR-2020	_____ ENC	as of ____/____/____

PROPELLER NOSERIAL/PART: KX958/968291303 **MODEL:** HC-E4A-3 **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 31-MAY-2011	LAST ACTUALS		CURRENT ACTUAL	
0 PROP HRS 0 A/C HRS	2654.9 PROP HRS	as of 07-APR-2020	_____ PROP HRS	as of ____/____/____



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05001B (s)	28 DAY CHECK							
	PKG 15	DAYS	28					
	REF:	HRS/MSC						
		AFL						
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 16 in PKG 17,18,19,20,21,22	MOS				27-NOV-2019	PKG	
	REF: AMM 05-20-00	HRS/MSC	A/R			2569.8		
		AFL						
05401A	300 HOUR INSPECTION							
+	PKG 17	MOS				27-NOV-2019		
	REF: AMM 05-40-01	HRS/MSC	300	+30/-30		2569.8	2869.8	2899.8
		AFL						
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 18	MOS	12		-7	27-NOV-2019	30-NOV-2020	
	REF: AMM 05-40-01	HRS/MSC	300	+30/-30		2569.8	2869.8	2899.8
		AFL						
05403A	600 HOUR INSPECTION							
+	PKG 19	MOS				27-NOV-2019		
	REF: AMM 05-40-01	HRS/MSC	600	+60/-60		2569.8	3169.8	3229.8
		AFL						



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 20	MOS	12			27-NOV-2019	30-NOV-2020	
		HRS/MSC	600	+60/-60		2569.8	3169.8	3229.8
	REF: AMM 05-40-01	AFL						
05405A	1200 HOUR OR 12 MONTH INSPECTION							
+	PKG 21	MOS	12			27-NOV-2019	30-NOV-2020	
		HRS/MSC	1200	+120/-120		2569.8	3769.8	3889.8
	REF: AMM 05-40-01	AFL						
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+	PKG 22	MOS	24	+1m/-1m		27-NOV-2019	31-DEC-2021	06-JAN-2022
		HRS/MSC	2400	+60/-60	9	2569.8	4969.8	5029.8
	REF: AMM 05-40-01	AFL						
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0296 Part # 3072955-01								
057010	NO. 1 ENGINE - MINOR INSPECTION							
	PKG 0	MOS				27-NOV-2019		
		HRS/MSC	300	+10%/-10%		2569.8	(2869.8) 2869.8	2899.8
	REF: See Workcard	ENC						



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00/121 (s)	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS						27-NOV-2019	
	REF: GENERIC NO REF	HRS/MSC	A/R					2569.8	
		AFL							
00-00/122 (s)	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS						27-NOV-2019	
	REF:	HRS/MSC	A/R					2569.8	
		AFL							
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS						27-NOV-2019	
	REF: GENERIC NO REF	HRS/MSC	A/R					2569.8	
		AFL							
P47E-111209	REVIEW AMM PC12/47E CHAPTER 4 & CHAPTER 5 REVISION 6 - CAMP CHANGE FORM								
05.150		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC	-						
		AFL							
P47E-160729	REVIEW PILATUS PC-12/47E REVISION AMM 15								
		MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC	-						
		AFL							
P47E-161217	REVIEW PILATUS PC-12/47E REVISION AMM 16								
		MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC	-						
		AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-180213	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 18	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-180524	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 19	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
	NEW REQUIREMENT ADDED ON 17-MAR-2020 (EFFECTIVE: 21-NOV-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									
E072-160317	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 25	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E072-160919	NO. 1 ENGINE - REVIEW PT6A-67B/-67P SB PT6A-72-14603 REV 26	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-170113	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 44.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							
E072-180821	NO. 1 ENGINE - REVIEW PT6A-67B/-67P EMM REV 47.2	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E072	HRS/MSC - ENC							

PROPELLER NO. 1 Model : HC-E4A-3 Serial # KX958 Part # 968291303

P019-160801	NO. 1 PROPELLER - REVIEW HC-E4A-3 SL REV 10 REQUIREMENT SUMMARY CHANGE FORM	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							
P019-171001	NO. 1 PROPELLER - REVIEW HARTZELL HC-E4A-3 POM 149 REV 23	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P019	HRS/MSC -							

CHAPTER 01 LIMITATIONS

0102PA	PERFORM FLIGHT LOG AUDIT	MOS	6				26-FEB-2019	31-JUL-2020 M	
CUSTOMER CODE	REF:	HRS/MSC AFL					2391.47 1723		

CHAPTER 04 LIMITATIONS

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
040001	AIRCRAFT LIMIT OF VALIDITY								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	50000	N:0			0		50000
LIFE LIMIT	REF:	AFL	60000	N:0			0		60000
<hr/>									
040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF:	AFL	43000	N:0			0		43000
<hr/>									
040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	35000	N:0			0		35000
LIFE LIMIT	REF:	AFL	43000	N:0			0		43000
<hr/>									
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)								
		MOS					27-DEC-2011		
		HRS/MSC	25000				0		25000
	REF: AMM 05-10-30	AFL	30000				0		30000
<hr/>									
050005	AIRCRAFT REGISTRATION - FAR 47.40								
		MOS	36				24-APR-2019		30-JUN-2022 M
		HRS/MSC					2423.3		
	REF:	AFL					1749		
<hr/>									
050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION								
		MOS					27-DEC-2011		
		HRS/MSC	25000				0		25000
	REF:	AFL	30000				0		30000
<hr/>									
CHAPTER 06	DIMENSIONS AND AREAS								

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
06-00/119 (s)	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION PKG 16 ,17,18,19,20,21,22 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		
06-00/123 (s)	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT PKG 16 ,17,18,19,20,21,22 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		
06-00/218 (s)	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR. PKG 16 ,17,18,19,20,21,22 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		
06-00/219 (s)	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOIN THE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB PKG 16 ,17,18,19,20,21,22 REF:	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		
CHAPTER 07 LIFTING AND SHORING									
07-10/160 (s)	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 16 ,17,18,19,20,21,22 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		
07-10/161 (s)	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION PKG 16 ,17,18,19,20,21,22 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 27-NOV-2019 2569.8		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
080000	WEIGHT CHECK AIRCRAFT								
08.005	REF:	MOS HRS/MSC AFL	36				11-DEC-2017 2027.02 1477	31-DEC-2020	
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 18	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
CHAPTER 11 PLACARDS AND MARKINGS									
11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF: See Workcard	AFL							
CHAPTER 12 SERVICING									
12-20/124 (s)	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS HRS/MSC AFL	3				27-NOV-2019 2569.8		
	REF: AMM 12-20-01	AFL							
12-20/125 (s)	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS HRS/MSC AFL	A/R				27-NOV-2019 2569.8		
	REF: AMM 12-20-02	AFL							
12-20/126 (s)	CLEAN COCKPIT AND CABIN						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS HRS/MSC AFL	A/R				27-NOV-2019 2569.8		
	REF: AMM 12-20-03	AFL							
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
20.010	REF:	MOS HRS/MSC AFL	12	+1m/-1m		-8	27-NOV-2019 2569.8	30-NOV-2020	19-DEC-2020
00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
20.011	REF:	MOS HRS/MSC AFL	12	+1m/-1m		-8	27-NOV-2019 2569.8	30-NOV-2020	19-DEC-2020
CHAPTER 21 AIR CONDITIONING									
21-20/221 (s)	EXAMINE ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT						PKG		
	PKG 22	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
21-20/317	CHECK ECS EMERGENCY SHUT-OFF SYSTEM								
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	12 3000	+10%/-10%		9	27-NOV-2019 2569.8	31-DEC-2020 5569.8	12-JAN-2021
21-30/314	CHECK PRESSURIZATION SAFETY VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND								
21.030	REF: AMM 21-30-02	PN SN-UNKNOWN AFL	24 3000	+10%/-10% +10%/-10%		-8	27-NOV-2019 2569.8	30-NOV-2021 5569.8	31-JAN-2022 5869.8
21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
21.045	REF: AMM 21-30-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		9	27-NOV-2019 2569.8	31-DEC-2020 5569.8	12-JAN-2021



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
21.040	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	24 3000	+10%/-10% +10%/-10%		-8	27-NOV-2019 2569.8	30-NOV-2021 5569.8	31-JAN-2022 5869.8
21-40/128 (s)	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH						PKG		
	PKG 21 REF: AMM 21-43-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			11-DEC-2017 2027.02 1477		
21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH						PKG		
21.140	PKG 21 REF: AMM 21-40-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH						PKG		
21.150	9696781507 PKG 21 549007 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER						PKG		
21.080	5214112047 PKG 21 2870 REF: AMM 21-40-03	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
21.130	9738132216 322 REF: AMM 21-40-06	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		21	06-DEC-2016 1771.2 1303	31-DEC-2021 6571.2	27-JUN-2022 7051.2
21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
21.120	9738132214 317 REF: AMM 21-60-05	MOS HRS/MSC AFL	60 4800	+10%/-10% +10%/-10%		21	06-DEC-2016 1771.2 1303	31-DEC-2021 6571.2	27-JUN-2022 7051.2



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 19 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			27-NOV-2019 2569.8		
21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 19 REF: AMM 21-40-02	MOS HRS/MSC AFL	600	+10%/-10%			27-NOV-2019 2569.8		
21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
21-50/433 (s)	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)						PKG		
	9599022102 PKG 18 1201A REF: AMM 21-40-03	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			27-NOV-2019 2569.8		
21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022102 1201A REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	N/A				11-MAY-2017 1869.3 1368 887.9		
21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	9599022102 1201A REF: AMM 21-50-01	MOS HRS/MSC AFL	N/A				27-NOV-2019 2569.8		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	9599022102 1201A REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	500	+10%/-10%			27-NOV-2019 2569.8 1330.6	1830.6	1880.6
21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	9599022102 1201A REF: AMM 21-50-01	MOS HRS/MSC AFL ACH	500	+10%/-10%			27-NOV-2019 2569.8 1330.6	1830.6	1880.6
210005	OVERPRESSURE SWITCH								
21.340	9738115105 989 REF: AMM 21-40-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210010	REFRIGERATION PACK								
21.255	9599020111 1740 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210015	WATER INJECTOR								
21.370	9599020141 1713 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210020	DUCT TEMP SENSOR								
21.320	9599020121 2827 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210025	PRIM SHUT OFF VALVE								
21.290	9599020132 1710 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210030	HP SHUT OFF VALVE								
21.280	9599020131 1726 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210035	WATER SEPARATOR ASSY								
21.220	5214112047 2870 REF: AMM 21-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210040	TEMPCONTROL VALVE								
21.310	9599020136 1716 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	9599022102 1201A REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210046	VAPOR CYCLE COMPRESSOR MOTOR								
	1134104-9 5143 REF: GENERIC NO REF	MOS HRS/MSC AFL ACH	O/C				18-MAY-2018 2164.3 1570 1064.8		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	9599022121 588 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	9599022119 620 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	9599091122 103898-00298 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	9599091132 110-F0290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	9696781507 549007 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	9599022118 602 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	9696781507 548191 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210170	OVERPRESSURE SWITCH								
21.340	9738115106 1020 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	9599020160 1027 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210180	CABIN PRESSURE CONTROL UNIT								
21.530	9599091143 2119232-00306 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	9633011005 364 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	9738132216 322 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	9738132214 317 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	9633011105 1024B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 1497B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	9633011106 1507B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	9633011106 1504B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
213050	RUN VAPOR CYCLE COOLING SYSTEM FOR 15 MINUTES								
21.050		DAYS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
21C006	ECS CONTROLLER,6130C000-002								
	9599020129 333 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		

CHAPTER 22 AUTO FLIGHT

22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES						PKG		
	PKG 22	MOS	24	+10%/-10%			27-NOV-2019		
	REF:	HRS/MSC	2400	+10%/-10%			2569.8		
		AFL							
22-10/60	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m	-8		27-NOV-2019	30-NOV-2020	19-DEC-2020
	REF: AMM 22-10-00	HRS/MSC	1000	+10%/-10%			2569.8	3569.8	3669.8
		AFL							
22-10/60	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m	-8		27-NOV-2019	30-NOV-2020	19-DEC-2020
	REF: AMM 22-10-00	HRS/MSC	1000	+10%/-10%			2569.8	3569.8	3669.8
		AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10/60	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK REF: AMM 22-10-00	MOS HRS/MSC AFL	12 1000	+1m/-1m +10%/-10%		-8	27-NOV-2019 2569.8	30-NOV-2020 3569.8	19-DEC-2020 3669.8
22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8	PKG	
22-20/130 (s)	CHECK STICK PUSHER SYSTEM PKG 17 REF: AMM 22-20-00	MOS HRS/MSC AFL	300	+10%/-10%			27-NOV-2019 2569.8	PKG	
22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM PKG 21 REF: AMM 22-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8	PKG	
220045 22.220	STICK PUSHER SERVO 9786111103 80575 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		
220055 22.140	STICK PUSHER CAPSTAN 9786111124 80564 REF: AMM 22-20-06	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		
220060 22.230	STICK SHAKER 9786111143 1090 REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220070	STICK PUSHER								
22.170	9754423104 127459 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
220075	KMC 9200 FLIGHT CONTROLLER								
22.270	071-01597-0401 KMC9200-1184 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-NOV-2019 2569.8		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1912 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1910 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	9859912133 KSM375-B1917 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
220100	RUDDER KSA 2700 SERVO								
22.260	9859912131 KSA2700-1723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-SEP-2015 1448.2 1114		
220105	ELEVATOR KSA 2700 SERVO								
22.250	9859912131 KSA2700-1913 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220110	AILERON KSA 2700 SERVO								
	9859912131	MOS		N:0			27-DEC-2011		
22.240	KSA2700-1914	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 23 COMMUNICATIONS									
23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH						PKG		
	PKG 22	MOS	24	+10%/-10%			27-NOV-2019		
		HRS/MSC	2400	+10%/-10%			2569.8		
	REF: AMM 23-50-00	AFL							
23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH						PKG		
	PKG 22	MOS	24	+10%/-10%			27-NOV-2019		
		HRS/MSC	2400	+10%/-10%			2569.8		
	REF: AMM 23-12-00	AFL							
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
	9848110203	MOS		N:0			27-DEC-2011		
23.020	310-21500	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-02	AFL		N:0			0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
	9848110203	MOS		N:0			27-DEC-2011		
23.030	310-21493	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-03	AFL		N:0			0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
	9848110210	MOS		N:0			27-DEC-2011		
23.070	11276	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-57-02	AFL		N:0			0		
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
	069-01037-0102	MOS					06-DEC-2012		
23.090	2944	HRS/MSC	O/C				436.7		
	REF: AMM 23-12-01	AFL					340		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.080	069-01037-0102 2784 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C				26-AUG-2014 1082.4 832		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	9859912108 G0777 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	9859912108 G0778 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
CHAPTER 24 ELECTRICAL POWER									
24-30/309 (s)	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437)						PKG		
24.210	978.91.23.407 PKG 17 P1620 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				27-NOV-2019 2569.8		
24-30/310 (s)	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.437)						PKG		
24.026	978.91.23.407 PKG 17 P1591 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				27-NOV-2019 2569.8		
24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		9	27-NOV-2019 2569.8	31-DEC-2020 5569.8	12-JAN-2021
AIRWORTHINESS									
24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		9	27-NOV-2019 2569.8	31-DEC-2020 5569.8	12-JAN-2021
AIRWORTHINESS									



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST PKG 22 REF: AMM 24-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST PKG 21 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
24-30/339 24.060	REMOVE AND SERVICE NO. 1 NICAD BATTERY 31406-002 11002490 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8	30-NOV-2020 2969.8	02-JAN-2021 3009.8
24-30/339 24.061	REMOVE AND SERVICE NO. 2 NICAD BATTERY 31406-002 10801465 REF: See Workcard	MOS HRS/MSC AFL	12 400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8	30-NOV-2020 2969.8	02-JAN-2021 3009.8
+ 24-30/473 (s)	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407) 978.91.23.407 PKG 19 P1620 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			PKG 27-NOV-2019 2569.8		
+ 24-30/474 (s)	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407) 978.91.23.407 PKG 19 P1591 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			PKG 27-NOV-2019 2569.8		
24-30/492 OVERHAUL	OVERHAUL NO. 1 STARTER GENERATOR 978.91.23.407 P1620 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	+10%/-10%			27-NOV-2019 2569.8	3769.8	3889.8

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P1591 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+10%/-10%			27-NOV-2019 2569.8	3769.8	3889.8
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR 978.91.23.407 P1620 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A						
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P1591 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
24-50/70 24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 501-1712-02 82477 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%	-8		27-NOV-2019 2569.8	30-NOV-2020	25-DEC-2020
24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	9882114111 P2645 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
240005-2	REGULATOR,VOLTAGE,51538-002A								
24.130	9882114111 P2640 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
240010	GENERATOR 1 300A CONTACTOR								
24.130	9740338113 P775 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
240015	GENERATOR 2 300A CONTACTOR								
24.130	9740338113 P696 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
243010	NO. 2 STARTER-GENERATOR								
24.215	978.91.23.407 P1591 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-NOV-2019 2569.8		
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 82477 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				06-DEC-2016 1771.2 1303		
243100	NO. 1 NICAD BATTERY								
24.060	31406-002 11002490 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C				02-AUG-2019 2489.2 1800		
243105	NO. 2 NICAD BATTERY								
24.061	31406-002 10801465 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	O:11 O:217.5 O:151			02-AUG-2019 2489.2 1800		
243160	NO. 1 STARTER GENERATOR								
24.205	978.91.23.407 P1620 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-NOV-2019 2569.8		
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	SS50 4709 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-FEB-2016 1596.6		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	9755085111 N1679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	9755085111 N1668 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 25 EQUIPMENT/FURNISHINGS

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-10/134 (s)	EXAMINE CREW SEAT BELTS PKG 18	MOS	12	+10%/-10%			PKG		
	REF:	HRS/MSC	300	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED PKG 17	MOS					PKG		
	REF:	HRS/MSC	300	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
25-10/294	CREW SEAT BELTS								
25.030	PN	MOS	144	+6m/-6m	N:0		27-DEC-2011	31-DEC-2023	27-JUN-2024
OVERHAUL	SN-UNKNOWN	HRS/MSC			N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
25-10/296 (s)	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 16 ,17,18,19,20,21,22	MOS					PKG		
	REF: AMM 25-10-01	HRS/MSC	A/R				27-NOV-2019		
		AFL					2569.8		
25-10/297 (s)	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 16 ,17,18,19,20,21,22	MOS					PKG		
	REF: AMM 25-10-01	HRS/MSC	A/R				27-NOV-2019		
		AFL					2569.8		
25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 21	MOS	12	+10%/-10%			PKG		
	REF: AMM 25-10-01	HRS/MSC	1200	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 18	MOS	12	+10%/-10%			PKG		
	REF:	HRS/MSC	300	+10%/-10%			27-NOV-2019		
		AFL					2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF:	AFL							
25-20/295	PASSENGER SEAT BELTS								
	PN	MOS	144	+6m/-6m	N:0		27-DEC-2011	31-DEC-2023	27-JUN-2024
25.010	SN-UNKNOWN	HRS/MSC			N:0		0		
OVERHAUL	REF: GENERIC NO REF	AFL			N:0		0		
25-20/298 (s)	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
		HRS/MSC	A/R				2569.8		
	REF: See Workcard	AFL							
25-20/299 (s)	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
		HRS/MSC	A/R				2569.8		
	REF: See Workcard	AFL							
25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION.						PKG		
	PKG 17	MOS					27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF:	AFL							
25-60/231 (s)	OPERATIONAL TEST ELT						PKG		
	9851380853 PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
	RX1000019129	HRS/MSC	300	+10%/-10%			2569.8		
	REF: AMM 25-63-00	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60/232 (s)	EXAMINE ELT INSTALLATION PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
25-63/23	ELT BATTERY S1820516-99	MOS		N:2			06-DEC-2016	01-JUL-2023 M	
25.020	TM0000087925	HRS/MSC	DUE	N:0			1771.2		
DISCARD	REF: GENERIC NO REF	AFL		N:0			1303		
25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED)								
	9851380858	MOS	120	+6m/-6m			27-DEC-2011	31-DEC-2021	27-JUN-2022
	2623069-0016	HRS/MSC	16000	+500/-500			0	16000	16500
DISCARD	REF:	AFL					0		
250005	REMOTE CONTROL PANEL 9851380817	MOS		N:0			27-DEC-2011		
25.070	TM0000016292	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
250010	EMERGENCY LOCATOR TRANSMITTER 9851380853	MOS		N:0			27-DEC-2011		
25.050	RX1000019129	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-63-00	AFL		N:0			0		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE 9851380858	MOS		N:0			27-DEC-2011		
25.060	2623069-0016	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-63-03	AFL		N:0			0		
250A93 (s)	VISUALLY INSPECT FIRST AID KITS PKG 15	DAYS	28				PKG		
	REF:	HRS/MSC AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250A94 (s)	VISUALLY INSPECT CREW LIFE VESTS PKG 15	DAYS	28				PKG		
	REF:	AFL							
250A95 (s)	VISUALLY INSPECT PASSENGER LIFE VESTS PKG 15	DAYS	28				PKG		
	REF:	AFL							
256015	CABLE ,S1825503-01 ASSEMBLY 9851380859	MOS		N:0			27-DEC-2011		
25.080	TM0000024882	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
256020	LH BLACK PILOT SEAT 9593001165	MOS		N:0			27-DEC-2011		
25.090	62409	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-10-01	AFL		N:0			0		
256025	RH BLACK CO-PILOT SEAT 9593001166	MOS		N:0			27-DEC-2011		
25.100	62304	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-10-01	AFL		N:0			0		
256A51 (s)	VISUALLY INSPECT COCKPIT FLASH LIGHTS PKG 15	DAYS	28				PKG		
	REF:	AFL							
256A52 (s)	VISUALLY INSPECT CABIN BRIEFING CARDS PKG 15	DAYS	28				PKG		
	REF:	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256A54 (s)	CHECK COMPANY MANUALS FOR REVISION STATUS AND CONDITION - GOM, GMM, MEL, RVSM AND INSPECTION PROGRAM						PKG		
	PKG 15	DAYS	28						
	REF:	HRS/MSC							
		AFL							
256A74 (s)	VISUALLY INSPECT LIFE RAFTS AND SURVIVAL KITS						PKG		
	PKG 15	DAYS	28						
	REF:	HRS/MSC							
		AFL							
256D75 (s)	VISUALLY INSPECT DEFIBRILLATOR PADS AND BATTERY						PKG		
	PKG 15	DAYS	28						
	REF:	HRS/MSC							
		AFL							
256K46 (s)	VISUALLY INSPECT FLARE GUN KIT						PKG		
	PKG 15	DAYS	28						
	REF:	HRS/MSC							
		AFL							
258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)								
25.110		MOS	12		-19		27-NOV-2019	30-NOV-2020	
	REF: AMM 25-63-00	HRS/MSC					2569.8		
		AFL							
25AX03 (s)	VISUALLY INSPECT CRASH AXE						PKG		
	PKG 15	DAYS	28						
	REF:	HRS/MSC							
		AFL							
25C019	PAX SEAT LH AFSS,403150-7-CF								
	9593001821	MOS		N:0			31-MAY-2011		
	49606	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C020	PAX SEAT RH AFSS,403150-8-CF 9593001822 49607 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C021	PAX SEAT LH FFSS,403150-9-BCF 9593001837 49609 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C022	PAX SEAT RH FFSS,403150-10-BCF 9593001838 49611 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C023	PC12/47E ENTERTAINMENT SYSTEM 5250512017 102 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C024	PAX SEAT LEFT,STANDARD 5252212011 1506 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C025	PAX SEAT RIGHT,STANDARD 5252212012 1527 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C026	PAX SEAT LH FFSS,403150-9-CF 9593001835 49608 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25C027	PAX SEAT RH FFSS,403150-10-CF 9593001836 49610 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
25C050	ELT REGISTRATION REF:	MOS HRS/MSC AFL	24				24-APR-2019 2423.3 1749	24-APR-2021 M	
CHAPTER 26 FIRE PROTECTION									
26-20/2	CABIN FIRE EXTINGUISHER 1.5 KG PN 26.030 SN-UNKNOWN REF: AMM 25-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
26-20/2	COCKPIT FIRE EXTINGUISHER C352TS 26.010 A-40841741 LIFE LIMIT REF: AMM 25-10-06	MOS HRS/MSC AFL	120	N:0 N:0 N:0			24-NOV-2015 1530.3 1163	30-NOV-2025	
26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224) C352TS 26.010 A-40841741 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+1m/-1m	-3		27-NOV-2019 2569.8	30-NOV-2020	24-DEC-2020
260005	FIRE/OVERHEAT DETECTOR 9751210012 26.020 211463 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
262A86 (s)	VISUALLY INSPECT COCKPIT FIRE EXTINGUISHER PKG 15 REF:	DAYS HRS/MSC AFL	28						PKG

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262A87 (s)	VISUALLY INSPECT CABIN FIRE EXTINGUISHER PKG 15	DAYS	28				PKG		
	REF:	AFL							
CHAPTER 27 FLIGHT CONTROLS									
27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL PKG 17	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES	MOS					27-DEC-2011		
27.255	REF:	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK	MOS	60	+10%/-10%			06-DEC-2016	31-DEC-2021	27-JUN-2022
27.010	REF: AMM 27-00-00	HRS/MSC	4800	+10%/-10%	21		1771.2	6571.2	7051.2
		AFL					1303		
27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001) PKG 18	MOS	12	+10%/-10%			PKG		
	REF:	HRS/MSC	300	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING PKG 21	MOS	12	+10%/-10%			PKG		
	REF:	HRS/MSC	1200	+10%/-10%			27-NOV-2019		
		AFL					2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	AFL	1200	+10%/-10%					
27-10/236 (s)	AILERON CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	AFL	1200	+10%/-10%					
27-10/237 (s)	CHECK AILERON CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 27-10-00	AFL	1200	+10%/-10%					
27-10/238 (s)	FUNCTIONAL TEST AILERONS PKG 22	MOS	24	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 27-10-00	AFL	2400	+10%/-10%					
27-10/394	AILERON CONTROL SYSTEM - EXAMINE	MOS					27-DEC-2011		
27.155		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-10-00	AFL	42000				0	42000	
27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT	MOS					27-DEC-2011		
27.160		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-10-09	AFL	42000				0	42000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS								
		MOS					27-DEC-2011		
27.165		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
		MOS					27-DEC-2011		
27.170		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS								
		MOS					27-DEC-2011		
27.175		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: See Workcard	AFL	42000				0		42000
+ 27-10/444	FLIGHT CONTROL CABLES, AILERON								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
+ 27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF: AMM 27-10-00	AFL							
27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM						PKG		
	PKG 22	MOS	24	+10%/-10%			27-NOV-2019		
		HRS/MSC	2400	+10%/-10%			2569.8		
	REF: AMM 27-15-00	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/140 (s)	INSPECTION/CHECK RUDDER PKG 18 REF: AMM 55-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-20/241 (s)	RUDDER CONTROL - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 21 REF: AMM 27-20-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 22 REF: AMM 27-20-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 22 REF: AMM 27-25-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	AFL	1200	+10%/-10%					
27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					27-DEC-2011		
27.180		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-00	AFL	42000				0	42000	
27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS	MOS					27-DEC-2011		
27.185		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-04	AFL	42000				0	42000	
27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT	MOS					27-DEC-2011		
27.190		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 27-20-05	AFL	42000				0	42000	
27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS					14-NOV-2013		
		HRS/MSC	O/C				803		
	REF: AMM 27-20-00	AFL					603		
27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)	MOS					27-DEC-2011		
	PN	HRS/MSC	A/R				0		
	REF: AMM 27-20-00	AFL					0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/446	FLIGHT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
<hr/>									
+ 27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
<hr/>									
27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF:	AFL							
<hr/>									
27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF:	AFL							
<hr/>									
27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS						PKG		
	PKG 22	MOS	24	+10%/-10%			27-NOV-2019		
		HRS/MSC	2400	+10%/-10%			2569.8		
	REF:	AFL							
<hr/>									
27-30/249 (s)	ELEVATOR CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF:	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 21	MOS	12	+10%/-10%			PKG	27-NOV-2019	
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%			2569.8		
27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 22	MOS	24	+10%/-10%			PKG	27-NOV-2019	
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%			2569.8		
27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED	MOS						14-NOV-2013	
27.150	REF: AMM 27-30-00	HRS/MSC AFL	O/C				803		
							603		
27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR)	MOS						27-DEC-2011	
	PN	HRS/MSC	A/R				0		
	SN-UNKNOWN	AFL					0		
	REF: AMM 27-30-00								
27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE	MOS						27-DEC-2011	
27.195	REF: AMM 27-30-00	HRS/MSC	32500				0		32500
AIRWORTHINESS		AFL	42000				0		42000
27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS	MOS						27-DEC-2011	
27.200	REF: AMM 27-00-01	HRS/MSC	32500				0		32500
AIRWORTHINESS		AFL	42000				0		42000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
		MOS					27-DEC-2011		
27.205		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-00-01	AFL	42000				0		42000
27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
		MOS					27-DEC-2011		
27.210		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 27-30-05	AFL	42000				0		42000
27-30/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
		MOS					27-DEC-2011		
27.215		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 57-60-06	AFL	42000				0		42000
+ 27-30/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
		MOS					27-DEC-2011		
		HRS/MSC	32500				0		32500
AIRWORTHINESS	REF: AMM 57-60-06	AFL	42000				0		42000
+ 27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
+ 27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000
+ 27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF:	AFL	27000	N:0			0		27000



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30/514 (s)	EXAMINE - ELEVATOR STOPS PKG 21 REF: AMM 55-20-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-DEC-2011 0 0		
27-40/1 27.021 AIRWORTHINESS	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR) REF: AMM 27-40-00	MOS HRS/MSC AFL	12 3000	+10%/-10%	-4		27-NOV-2019 2569.8	30-NOV-2020 5569.8	29-DEC-2020
27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES PKG 18 REF: AMM 27-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
+ 27-40/26 OVERHAUL	OVERHAUL PITCH TRIM ACTUATOR 129-1-1100-02 1049 REF:	MOS HRS/MSC AFL	84 3400		I:1 I:0		20-NOV-2014 1159.5 897	31-OCT-2021 4559.5	
27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 17 REF: AMM 27-40-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 27-NOV-2019 2569.8		
27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM PKG 21 REF: AMM 27-40-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40/3	REPLACE PITCH TRIM ACTUATOR 129-1-1100-02 1049	MOS HRS/MSC	20000	1:865.9			20-NOV-2014 1159.5		20293.6
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	1:478			897		27419
27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7) PN	MOS		N:0			27-DEC-2011		
27.036	SN-UNKNOWN	HRS/MSC	10000	N:0			0		10000
LIFE LIMIT	REF: AMM 27-40-02	AFL		N:0			0		
27-50/143 (s)	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 16 , 17,18,19,20,21,22	MOS HRS/MSC A/R					27-NOV-2019 2569.8		
	REF: GENERIC NO REF	AFL							
27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 18	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 21	MOS HRS/MSC	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 21	MOS HRS/MSC	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 21	MOS HRS/MSC	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 27-50-00	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/28	FLAP POWER DRIVE UNIT								
	9787320003	MOS		N:0			27-DEC-2011		
27.030	1016	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
OVERHAUL	REF: AMM 27-50-01	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR								
	9787320309	MOS					27-DEC-2011		
27.040	4093	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS					27-DEC-2011		
27.041	4117	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR								
	9787320309	MOS					27-DEC-2011		
27.050	4062	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS					27-DEC-2011		
27.051	4103	HRS/MSC	5000	+10%/-10%			0	5000	5500
OVERHAUL	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			27-DEC-2011		
27.060	S6772	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			27-DEC-2011		
27.060	S6817	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202205	MOS		N:0			27-DEC-2011		
27.070	S6774	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
	9450202206	MOS		N:0			27-DEC-2011		
27.070	S6821	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
DISCARD	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
27-50/386	FLAP MECHANISM - EXAMINE								
		MOS					27-DEC-2011		
27.220		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	39000				0	39000	
27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
		MOS					27-DEC-2011		
27.225		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 27-51-00	AFL	30000				0	30000	
27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
		MOS					27-DEC-2011		
27.230		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
		MOS					27-DEC-2011		
27.235		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS					27-DEC-2011		
		HRS/MSC	30000				0	30000	
AIRWORTHINESS	REF: See Workcard	AFL	39000				0	39000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS								
		MOS					27-DEC-2011		
27.240		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
<hr/>									
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS								
		MOS					27-DEC-2011		
		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
<hr/>									
27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
		MOS					27-DEC-2011		
27.245		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
<hr/>									
27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
		MOS					27-DEC-2011		
27.250		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: See Workcard	AFL	39000				0		39000
<hr/>									
27-50/4	LEFT INBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		27-DEC-2011		
27.040	4093	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000
<hr/>									
27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		27-DEC-2011		
27.041	4117	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000
<hr/>									
27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	9787320309	MOS			N:0		27-DEC-2011		
27.050	4062	HRS/MSC	20000		N:0		0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000		N:0		0		27000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	9787320309	MOS		N:0			27-DEC-2011		
27.051	4103	HRS/MSC	20000	N:0			0	20000	
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0	27000	
27-50/414	LEFT HAND FLAP								
	557.50.12.003	MOS		N:0			07-JAN-2014		
57.060	6005S	HRS/MSC	25000	N:0			865.1	25865.1	
LIFE LIMIT	REF:	AFL	30000	N:0			646	30646	
27-50/414	RIGHT HAND FLAP								
	5575012004	MOS		N:0			27-DEC-2011		
57.060	1077P	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF:	AFL	30000	N:0			0	30000	
27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%			27-NOV-2019	30-NOV-2020	26-DEC-2020
		HRS/MSC	600	+10%/-10%	-7		2569.8	3169.8	3229.8
AIRWORTHINESS	REF: AMM 27-51-00	AFL							
27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF: AMM 12-20-07	AFL							
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF:	AFL	27000	N:0			0	27000	
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
		HRS/MSC	A/R				2569.8		
	REF:	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/74 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR						PKG		
27.040	9787320309 PKG 18 4093 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
27-50/74 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR						PKG		
27.041	9787320309 PKG 18 4117 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			27-NOV-2019 2569.8		
27-50/74 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR						PKG		
27.050	9787320309 PKG 18 4062 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			27-NOV-2019 2569.8		
27-50/74 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR						PKG		
27.051	9787320309 PKG 18 4103 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			27-NOV-2019 2569.8		
27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR								
27.040	9787320309 4093 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			27-NOV-2019 2569.8 1850	30-NOV-2021 4969.8 5050	08-FEB-2022 5209.8 5370
27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR								
27.041	9787320309 4117 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			27-NOV-2019 2569.8 1850	30-NOV-2021 4969.8 5050	08-FEB-2022 5209.8 5370
27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR								
27.050	9787320309 4062 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			27-NOV-2019 2569.8 1850	30-NOV-2021 4969.8 5050	08-FEB-2022 5209.8 5370

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	9787320309 4103 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			27-NOV-2019 2569.8 1850	30-NOV-2021 4969.8 5050	08-FEB-2022 5209.8 5370
270003	HORIZONTAL TAIL ASSY								
	5551012037 1095 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270015	ELEVATOR LH ASSY								
27.015	5552012039 1131 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270023	ELEVATOR RH ASSY								
27.023	5552012040 1134 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR								
27.090	9787318138 444 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270030	FIN ASSY								
27.031	5553012041 1075P REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270033	RUDDER ASSY								
27.033	5554012040 1078P REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270035	FLAP CONTROL AND WARNING UNIT								
27.130	978.73.20.017 125116 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			22-FEB-2013 537.8 417		
270045	LH INBOARD TRANSMITTER								
27.100	9787320021 10N050DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270050	LH ROTATION TRANSMITTER								
27.120	9787320602 1687 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	9787320021 10N019DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	9787320021 11012DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	9787320602 1685 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270080	KTA2810,TRIM ADAPTER								
22.135	065-00195-0100 KTA2810-1556 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-DEC-2012 436.7 340		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270090	AILERON LINEAR ACTUATOR								
27.140	9787318138 428 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	9787320021 10N020DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
274020	PITCH TRIM ACTUATOR								
	129-1-1100-02 1049 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	O:1 N:865.9 O:0 N:478 O:0			20-NOV-2014 1159.5 897		
CHAPTER 28 FUEL									
28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 18	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 18	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL							
28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029	REF: AMM 28-10-01	MOS HRS/MSC AFL	2400	+10%/-10%	20.9		01-SEP-2017 1963.7 1437	4384.6	4624.6
28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 18	MOS HRS/MSC	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 28-20-07	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT PKG 18 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N) PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
28-20/32	OVERHAUL ENGINE DRIVEN PUMP 9688451108 28.010 OVERHAUL REF: AMM 28-20-03	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		27-DEC-2011 0 0	3500	3850
280005	LOW PRESSURE FUEL PUMP 9688451108 28.120 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280010	FUEL FLOW TRANSMITTER								
28.130	975.35.12.108 AAC3445 REF: AMM 73-30-01	MOS HRS/MSC AFL	O/C				11-APR-2015 1306.8 1001		
280012	FUEL CONTROL MONITORING UNIT								
28.155	975.37.31.336 382 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-MAR-2013 606 452		
280015	FIREWALL FUEL,SHUT-OFF VALVE								
28.110	9638722301 2682 REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	9638722301 2683 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280025	FUEL FILTER ASSY								
28.025	9683521001 2010FFT3563 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280030	FUEL LOW PRESSURE SWITCH								
28.100	9738114102 1988 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280035	EJECTOR,TRANSFER LH PUMP								
28.040	9688471104 B4690 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280040	EJECTOR,DELIVERY LH PUMP								
28.030	9688471105 B4869 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	9753731220 952 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	9753731219 957 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	9753731218 939 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	9753731217 934 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	9688411405 B7422 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280070	EJECTOR,TRANSFER RH PUMP								
28.040	9688471104 B4681 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280075	EJECTOR,DELIVERY RH PUMP								
28.030	9688471105 B4868 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	9753731217 923 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	9753731218 956 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	9753731219 949 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	9753731220 967 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280100	FUEL,BOOSTER RH PUMP								
28.050	9688411405 B7540 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280105	TOP CHECK VALVE								
28.150	9630423105 2610 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280110	BOTTOM CHECK VALVE								
28.150	9630423105 2602 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	9753731333 762 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	9753731333 756 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
28C001	ANNUAL FUEL MICROBIAL CHECK								
		MOS HRS/MSC AFL	12				27-NOV-2019 2569.8	30-NOV-2020	
	REF:								

CHAPTER 29 HYDRAULIC POWER

29-10/151 (s)	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE						PKG		
	PKG 20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 29-10-04								
29-10/153 (s)	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY						PKG		
	PKG 18	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 29-00-00								

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10/257 (s)	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
29-10/258 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)						PKG		
	9603001292 PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
	1162L	HRS/MSC	1200	+10%/-10%				2569.8	
	REF: AMM 29-10-02	AFL							
29-10/259 (s)	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
29-10/316 (s)	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.						PKG		
	PKG 18	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	300	+10%/-10%				2569.8	
	REF: AMM 29-00-00	AFL							
29-10/418	NITROGEN ACCUMULATOR (IF INSTALLED)								
	9603001292	MOS		N:0				27-DEC-2011	
29.020	1162L	HRS/MSC	25000	N:0				0	25000
LIFE LIMIT	REF:	AFL	30000	N:0				0	30000
+ 29-10/471 (s)	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)						PKG		
	9603001292 PKG 22	MOS	24	+10%/-10%				27-NOV-2019	
	1162L	HRS/MSC	2400	+10%/-10%				2569.8	
	REF: AMM 29-10-02	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
290020	ACTUATOR,LDG,NOSE 9603001111 2101A REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
290025	SERVICE SELECTOR VALVE 9603001261 G1021110A REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
290030	PRESSURE GAUGE 9656188101 10-081323 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
290040	HAND PUMP 9688582111 1103 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
290050	PRESSURE NITROGEN SWITCH 9738114306 1342 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
291010	HYDRAULIC POWER PACK 9603001154 G1020124 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 30 ICE AND RAIN PROTECTION

30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF: AMM 30-10-00	AFL							

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM PKG 20 REF: AMM 30-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM PKG 21 REF: AMM 30-10-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
30-10/79 30.010	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1 REF: GENERIC NO REF	MOS HRS/MSC AFL	6	+10%/-10%			27-NOV-2019 2569.8	31-MAY-2020	14-JUN-2020
30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 20 REF: AMM 30-30-20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 22 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 27-NOV-2019 2569.8		
30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 27-NOV-2019 2569.8		
300005 30.140	PROP DE-ICE CONTROLLER 9682913227 U1049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300010 30.150	LPMI LINEAR ACTUATOR 9787315302 C39194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300015 30.160	REGULATOR-RELIEVER ASSY 9598901012 N103125 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300020 30.110	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 9598901008 N101903 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300025 30.120	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE 9598901008 N101911 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	9598901008 N102268 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	9598901008 N102267 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	9738114312 5792 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300050	WATER SEPARATOR								
30.060	9598901010 N102683 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	9598901014 U1822 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 127620 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	9728132202 127622 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	27-7D5221-13 NDQ6570 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	27-7D5221-14 NEC5080 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		
300100	RH INBD-WING DE-ICER BOOT								
30.040	27-7D5221-10 NDQ9290 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	27-7D5221-12 NDE2920 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U2335 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	27-7D5221-09 NDQ4500 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	27-7D5221-11 NEO2830 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	9754421417 U2338 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	9738114312 5800 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	973.81.14.312 7452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-FEB-2015 1258.4 966		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 5819 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	9738114312 5818 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	9598901008 N102256 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 31 INDICATING/RECORDING SYSTEMS

31-30/421 (s)	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)						PKG
	PKG 21	MOS	12	+10%/-10%		27-NOV-2019	
		HRS/MSC	1200	+10%/-10%		2569.8	
	REF: AMM 31-30-01	AFL					

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310050	DIGITAL CLOCK								
31.040	9996111213 1067036 REF: AMM 31-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	071-01596-0201 KMC2210-1934 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			24-NOV-2015 1530.3 1163		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE								
31.240	7036410-1904 13019516 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				10-OCT-2013 783.3 592		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE								
31.270	7036410-1904 12119487 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C				10-OCT-2013 783.3 592		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD								
31.160	7038231-1801 13095277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			17-FEB-2014 900.2 672		
310090	KMC2220 MF CONTOLLER								
31.170	9859912189 KMC2220-1391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310095	PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	071-01596-0201 KMC2210-1588 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1012C512 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	9859912190 1011C392 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	9859912147 10084957 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	7038231-1801 13084850 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			17-FEB-2014 900.2 672		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	9859912143 1102K096 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	9859912143 1102K112 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	7038622-1901 14080950 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-NOV-2015 1530.3 1163		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	7036333-1906 15041589 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-NOV-2015 1530.3 1163		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	K9321022A00 1890160309 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			24-NOV-2015 1530.3 1163		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	9859912103 1890216351 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890216882 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	9859912103 1890141037 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0			24-MAR-2016 1631.9 1225		
310155	REV CTL PNL,4-POT DISPLAY								
31.130	9728121141 297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40028610 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	9858314204 40028647 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
31C044	CCD INTERNAL ELECTRICAL ASSEMBLY								
	9859912218 40 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
31C045	REAR CENTRE CONS PNL PC-12 47/E								
	9728121154 185 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
31C046	CVFDR								
	9859920136 688114 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
31C047	COCKPIT AREA MICROPHONE								
	9859920137 691948 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		

CHAPTER 32 LANDING GEAR

32-10/162 (s)	LUBRICATE MAIN LANDING GEAR						PKG		
	PKG 20	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	600	+10%/-10%			2569.8		
	REF: AMM 12-20-04	AFL							
32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS						PKG		
	PKG 20	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	600	+10%/-10%			2569.8		
	REF: GENERIC NO REF	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 20	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC	600	+10%/-10%					
		AFL							
32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 20	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 32-10-00	HRS/MSC	600	+10%/-10%					
		AFL							
32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC	1200	+10%/-10%					
		AFL							
32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK	MOS	12	+1m/-1m			27-NOV-2019	30-NOV-2020	19-DEC-2020
32.010	REF: See Workcard	HRS/MSC	2400	+10%/-10%	-8		2569.8	4969.8	5209.8
		AFL							
32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY 5321012054	MOS					27-DEC-2011		
32.070	VLG488	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					27-DEC-2011		
AIRWORTHINESS	REF:	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION	MOS					27-DEC-2011		
32.215	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
AIRWORTHINESS		AFL	30000				0	30000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					27-DEC-2011		
AIRWORTHINESS	REF:	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	
32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION	MOS					27-DEC-2011		
32.220		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF:	AFL	30000				0	30000	
32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	12	+10%/-10%	14		27-NOV-2019	31-DEC-2020	17-JAN-2021
	REF: See Workcard	HRS/MSC					2569.8		
		AFL							
32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2017	31-MAY-2023	
	REF: See Workcard	HRS/MSC					1869.3		
		AFL					1368		
32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS	72				11-MAY-2017	31-MAY-2023	
	REF: See Workcard	HRS/MSC					1869.3		
		AFL					1368		
32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS					27-DEC-2011		
	REF: AMM 32-10-00	HRS/MSC	N/A				0		
		AFL					0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
	REF: AMM 32-10-00								
32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
	REF: AMM 32-10-00								
32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
	REF: AMM 32-10-00								
32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
	REF: AMM 32-10-00								
32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	N/A				27-DEC-2011 0 0		
	REF: AMM 32-10-00								
32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS	MOS HRS/MSC AFL	12	+1m/-1m		-8	27-NOV-2019 2569.8	30-NOV-2020	19-DEC-2020
	PN SN-UNKNOWN REF: AMM 12-20-06								
32-10/80	LUBRICATE NOSE WHEEL BEARINGS	MOS HRS/MSC AFL	12	+1m/-1m		-8	27-NOV-2019 2569.8	30-NOV-2020	19-DEC-2020
	9595602302 1076 REF: AMM 12-20-06								



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS PN SN-UNKNOWN REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		-8	27-NOV-2019 2569.8	30-NOV-2020	19-DEC-2020
32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 20 REF: AMM 32-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 20 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 21 REF:	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-20/335	NOSE LANDING GEAR TORQUE TUBE PN SN-UNKNOWN LIFE LIMIT	MOS HRS/MSC AFL	120 11000 15000		N:0 N:0 N:0		27-DEC-2011 0 0	31-DEC-2021 11000 15000	



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
32.195	532.20.12.296 SN-UNKNOWN REF: AMM 32-20-06	MOS HRS/MSC AFL	N/A				01-SEP-2017 1963.7 1437		
32-20/403	NOSE LANDING GEAR - OVERHAUL								
32.200 OVERHAUL	PN SN-UNKNOWN REF: AMM 32-10-00	MOS HRS/MSC AFL	25000 30000	+500/-500 +500/-500	N:0 N:0 N:0		27-DEC-2011 0 0	25000 30000	25500 30500
32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
32.225 LIFE LIMIT	532.20.12.296 SN-UNKNOWN REF: AMM 32-20-05	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		27-DEC-2011 0 0	25000 30000	
32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM								
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
32-30/417	LEFT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
32.040 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		27-DEC-2011 0 0	25000 30000	
32-30/417	RIGHT HAND MAIN LANDING GEAR HYDRAULIC ACTUATOR								
32.040 LIFE LIMIT	9603001105 2326H REF:	MOS HRS/MSC AFL	25000 30000		N:0 N:0 N:0		27-DEC-2011 0 0	25000 30000	
32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: See Workcard	MOS HRS/MSC AFL	72				11-DEC-2017 2027.02 1477	31-DEC-2023	



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS REF: See Workcard	MOS HRS/MSC AFL	72				11-DEC-2017 2027.02 1477	31-DEC-2023	
32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		PKG
32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE PKG 18 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		PKG
32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS PKG 20 REF:	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		PKG
32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE PKG 18 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		PKG
32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING. PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		PKG



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY PKG 18	MOS	12	+10%/-10%			PKG		
	REF: AMM 12-10-02	HRS/MSC AFL	300	+10%/-10%			27-NOV-2019 2569.8		
32-50/404	EXAMINE - NLG STEERING MECHANISM	MOS					27-DEC-2011		
32.230	REF:	HRS/MSC AFL	32500 42000				0 0	32500 42000	
320005	PILOT LH BRAKE MASTER CYLINDER	MOS					27-DEC-2011		
32.130	9594751132 969 REF: AMM 32-40-04	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
320006	STEREER SELECTOR, LANDING GEAR VALVE	MOS					14-NOV-2013		
29.040	960.30.01.272 0916 REF: AMM 32-30-03	HRS/MSC AFL	O/C	O:1 O:0 O:0			803 603		
320010	PILOT RH BRAKE MASTER CYLINDER	MOS					27-DEC-2011		
32.130	9594751132 972 REF: AMM 32-40-04	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
320015	PARK BRAKE VALVE	MOS					27-DEC-2011		
32.140	9594751132 977 REF: AMM 32-40-05	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
320020	NOSE WHEEL	MOS					27-DEC-2011		
32.150	9595602302 1076 REF: AMM 32-40-02	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320021	NOSE LANDING GEAR TIRE 021-327-0 3352S00065 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C					27-JUL-2015 1404 1075	
320022	LEFT MAIN LANDING GEAR WHEEL PN SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:14 N:537.8 N:417				22-FEB-2013 537.8 417	
320023	LEFT MAIN LANDING GEAR TIRE 021-350-0 5327S00243 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:31 N:0 N:0				12-JUL-2018 2200.6	
320024	RIGHT MAIN LANDING GEAR WHEEL PN SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:14 N:537.8 N:417				22-FEB-2013 537.8 417	
320025	SHIMMY DAMPER ASSY 5322012215 SI-0195 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-DEC-2011 0 0	
320026	RIGHT MAIN LANDING GEAR TIRE 025-350-0 7270S00338 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				04-SEP-2018 2262.4 1647	
320030	COPILOT LH BRAKE MASTER CYLINDER 9594751132 977 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-DEC-2011 0 0	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	9594751132 983 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	5322012249 SI-0194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	5322012040 SI-0194 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG1006 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320060	LH BRAKE ASSY								
32.050	9595601517 1979 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	959.56.01.503 2087 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320066	OUTER LEFT WHEEL & COVER ASSY								
32.205	959.56.01.503 2110 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320080	LEFT SHOCK ABSORBER ASSY								
32.060	5321012211 VLG1007 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320085	RH BRAKE ASSY								
32.050	9595601517 2012 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	959.56.01.503 2089 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
320091	OUTER RIGHT WHEEL & COVER ASSY								
32.210	959.56.01.503 2112 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
32C055	BOLT								
	5323412062 1104 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
32C056	BOLT								
	5323412062 1166 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		

CHAPTER 33 LIGHTS

33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF: AMM 33-40-00	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 18 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 18 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
330005 33.080	DIM UNIT 9750215205 127537 REF: AMM 33-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330010 33.010	DE-ICE LIGHT ASSY 9728767111 1671232 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330015	LH HIDL WING								
33.020	9728769413 1605119 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330020	RH HIDL WING								
33.020	9728769413 1605124 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	9728787331 20439 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	9728787332 20468 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330035	LH WING POWER SUPPLY UNIT								
33.070	9728787164 42176 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 28288002 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-NOV-2018 2316.7 1678		
330045	RH WING POWER SUPPLY UNIT								
33.070	9728787164 42178 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.322 43754 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330055	NAVIGATION (FC), LED GREEN LIGHT								
33.050	9728787158 43301 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330060	NAVIGATION (FC), LED RED LIGHT								
33.050	9728787157 41851 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330065	NAVIGATION (FC), LED WHITE LIGHT								
33.060	9728787159 40737 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330075	L/H 1X0005287-10 LANDING LIGHT								
33.090	9728769402 1709859 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
330076	R/H 1X0005287-10 LANDING LIGHT								
33.110	9728769402 1709854 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER	NAVIGATION				
34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS				PKG
	PKG 22	MOS	24	+10%/-10%	27-NOV-2019
		HRS/MSC	2400	+10%/-10%	2569.8
	REF:	AFL			

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT PKG 18	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	300	+10%/-10%					
34-11/185 (s)	EXAMINE PITOT TUBE PKG 18	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	300	+10%/-10%					
34-11/186 (s)	EXAMINE STATIC PORTS PKG 18	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	300	+10%/-10%					
34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 34-11-00	HRS/MSC AFL	1200	+10%/-10%					
34-11/343 34.565	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT REF: AMM 34-11-12	MOS HRS/MSC AFL	24			-8	27-NOV-2019 2569.8	30-NOV-2021	
34-11/82 34.010	LEAK CHECK STATIC SYSTEM REF: AMM 34-11-00	MOS HRS/MSC AFL	24			-8	27-NOV-2019 2569.8	30-NOV-2021	
34-21/84 34.560	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED) REF: AMM 34-21-00	MOS HRS/MSC AFL	24	+10%/-10%		-4	27-NOV-2019 2569.8	30-NOV-2021	04-FEB-2022



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)								
34.570	REF: AMM 34-14-00	MOS HRS/MSC AFL	24	+10%/-10%		-4	27-NOV-2019 2569.8	30-NOV-2021	04-FEB-2022
34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)								
34.050	REF: See Workcard	MOS HRS/MSC AFL	24				27-NOV-2019 2569.8	30-NOV-2021	
340002	EGPWS PERFORM UPDATE EGPWS TERRAIN DATA BASE								
	REF:	MOS HRS/MSC AFL	12				27-NOV-2019 2569.8	30-NOV-2020	
340010	DME/IFF ANTENNA								
34.080	9848110240 261-103221 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		
340020	MARKER ANTENNA								
34.100	9848110260 101-7305 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		
340055	WITH HARM FILTER,KN63 DME								
34.200	9859911101 34351 REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		
340065	WX-RADAR RT UNIT								
34.360	9859911503 13317 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340075	WX,VERTICAL ANTENNA								
34.370	9859911504 6886 REF: AMM 34-41-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	9848110240 261-103181 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340085	ADF,KA44B ANTENNA								
34.070	9859911167 KA44B-A89660 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340100	FRONT KA92 ANTENNA								
34.090	9859911200 49307019 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	9859911200 49307020 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340105	LH NAV/GS ANTENNA								
34.380	9848110280 9515 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	9859911884 16841 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340135	STANDBY MAGNETIC COMPASS								
34.130	9999880103 AT-1177 REF: AMM 34-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340140	RADOME								
34.420	9857900005 11 REF: AMM 34-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	9848110412 6566 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-55628 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	9848129101 543-55617 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 23452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	9859911869 22186 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	9859911550 KRA405B-11023 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
3401PA	UPDATE NAV DATABASE PKG 15 REF:	DAYS HRS/MSC AFL	DUE				29-APR-2020 2651.2 1904	21-MAY-2020 M	
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	9859918006 96804 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340230	RH NAV/GS ANTENNA								
34.380	9848110280 9515 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340235	AOA SENSOR RH UNIT								
34.330	9754421424 1228 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	9859911505 CM2000-24089 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340246	ART 2000 RADAR								
	071-01519-0101 8474 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-NOV-2015 1530.3 1163		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340255	AOA SENSOR LH UNIT								
34.330	9754421423 1234 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	9848110240 261-103222 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340270	LEFT PITOT STATIC TUBE								
34.535	9651112302 1571603 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340275	RIGHT PITOT STATIC TUBE								
34.535	9651112302 1571703 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-2126 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	9859912114 KMG7010-2125 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	9859911887 KMH920-B1310 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-SEP-2015 1448.2 1114		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340310	NO. 2 KXP 2290 MODE S TRANSPONDER 066-01198-0102 KXP2290A-1699 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				20-NOV-2018 2316.7 1678		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER 066-01198-0102 KXP2290A-1701 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				20-NOV-2018 2316.7 1678		
340320	LH OAT SENSOR 5341312025 3713 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
340325	RH OAT SENSOR 5341312025 3857 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
34C000	AVIONICS INSPECTION PROGRAM REF:	MOS HRS/MSC AFL	24				27-NOV-2019 2569.8	30-NOV-2021	
34C001	ANNUAL AVIONICS INSPECTION REF:	MOS HRS/MSC AFL	12				27-NOV-2019 2569.8	30-NOV-2020	
34C002	INSPECTION OF ALTIMETER AND TRANSPONDERS IAW F.A.R. 91.411 AND 91.413 REF:	MOS HRS/MSC AFL	24				27-NOV-2019 2569.8	30-NOV-2021	



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34C005	RVSM REDUCED VERTICAL SEPARATION MINIMUM INSPECTION REF:	MOS HRS/MSC AFL	24				27-NOV-2019 2569.8	30-NOV-2021	
34C076	KGS200,SBAS GNSSU 066-01201-0105 KGS200-1654 REF:	MOS HRS/MSC AFL	O/C				06-DEC-2012 436.7 340		
34C077	KSG7200 DUAL CHANNEL ADAHRS 065-00188-5104 KSG7200-B2460 REF:	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			09-FEB-2016 1596.6		
34C078	KGS200,SBAS GNSSU 066-01201-0105 KGS200-1658 REF:	MOS HRS/MSC AFL	O/C				06-DEC-2012 436.7 340		
34C079	MAGNETOMETER MAG-3100 9859003058 80060 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
34C080	STANDBY SYSTEM ESI-1000 9759611247 1092 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-MAY-2011 0 0		
CHAPTER 35 OXYGEN									
35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS PKG 17	MOS HRS/MSC AFL	300	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:								
35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:								
35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM PKG 21	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 35-00-00								
35-10/6 (s)	OXYGEN BOTTLE PN SN-UNKNOWN	MOS HRS/MSC AFL	180		N:0 N:0 N:0		31-MAY-2011 0 0		
	REF: See Workcard								
35-10/6	REAR FUSELAGE OXYGEN CYLINDER 895-06077 C11010920	MOS HRS/MSC AFL	180				06-DEC-2016 1771.2 1303	30-SEP-2025	
	REF: See Workcard								
	Manufacture Date: 01-SEP-2010								
35-10/7 (s)	HYDROSTATIC TEST OXYGEN BOTTLE PN SN-UNKNOWN	MOS HRS/MSC AFL	60				27-DEC-2011 0 0		
	REF:								
35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER 895-06077 C11010920	MOS HRS/MSC AFL	60				23-NOV-2016	30-NOV-2021	
	REF:								



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)	MOS					27-NOV-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	400	+10%/-10%			2569.8	2969.8	3009.8
35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS	MOS	36	+10%/-10%			27-NOV-2019	30-NOV-2022	15-MAR-2023
35.010	REF: AMM 35-20-00	HRS/MSC AFL					2569.8		
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY	MOS					27-DEC-2011		
35.040	9571201210 SE58170 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY	MOS					27-DEC-2011		
35.040	9571201210 SE58176 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
350030	PRESSURE,GAGE,OXYGEN SWITCH	MOS					27-DEC-2011		
35.050	9738114401 1097 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
350035	CONTR,3-POSITION,37071-03 VALVE	MOS					27-DEC-2011		
35.030	9633211102 95 REF: AMM 35-20-04	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
350050	OXYGEN GAGE ASSY	MOS					27-DEC-2011		
35.060	5351212085 60153 REF: AMM 35-20-05	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
350055	OXYGEN PRESS TRANSDUCER	MOS					27-DEC-2011		
35.070	9571201184 7509-1-115 REF: GENERIC NO REF	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353829 (s)	VISUALLY INSPECT PORTABLE O2 BOTTLES PKG 15	DAYS	28				PKG		
	REF:	AFL							
CHAPTER 45 CENTRAL MAINT SYSTEM									
45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD PKG 21	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 45-45-00	AFL	1200	+10%/-10%					
CHAPTER 46 INFORMATION SYSTEMS									
46-26/320 (s)	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES PKG 18	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF: See Workcard	AFL	300	+10%/-10%					
46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES PKG 18	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF: AMM 46-30-02	AFL	300	+10%/-10%					
CHAPTER 52 DOORS									
52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK PKG 20	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL	600	+10%/-10%					
52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS PKG 20	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL	600	+10%/-10%					
52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS PKG 20	MOS	12	+10%/-10%			27-NOV-2019 2569.8		
	REF:	AFL	600	+10%/-10%					

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	600	+10%/-10%				2569.8	
	REF:	AFL							
52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
52.070		MOS						27-DEC-2011	
AIRWORTHINESS		HRS/MSC	32500					0	32500
	REF: AMM 52-10-00	AFL	42000					0	42000
52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE								
52.100		MOS						27-DEC-2011	
		HRS/MSC	32500					0	32500
	REF:	AFL	42000					0	42000
52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN								
52.110		MOS						27-DEC-2011	
		HRS/MSC	25000					0	25000
	REF:	AFL	30000					0	30000
52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
52.010		MOS	72	+6m/-6m	16			11-DEC-2017	31-DEC-2023
		HRS/MSC	6000	+500/-500				2027.02	8027.02
	REF: See Workcard	AFL						1477	27-JUN-2024 8527.02
52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED)						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR								
		MOS						27-DEC-2011	
52.080		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 52-20-00	AFL	42000					0	42000
52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 20	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	600	+10%/-10%				2569.8	
	REF:	AFL							
52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM.						PKG		
	PKG 20	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	600	+10%/-10%				2569.8	
	REF: AMM 52-30-00	AFL							
52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 20	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	600	+10%/-10%				2569.8	
	REF:	AFL							
52-30/274 (s)	EXAMINE CARGO DOOR						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
		MOS						27-DEC-2011	
52.090		HRS/MSC	32500					0	32500
AIRWORTHINESS	REF: AMM 52-30-00	AFL	42000					0	42000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
52.120		MOS					27-DEC-2011		
		HRS/MSC	32500				0		32500
	REF:	AFL	42000				0		42000
52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
52.130		MOS					27-DEC-2011		
		HRS/MSC	25000				0		25000
	REF:	AFL	30000				0		30000
52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
52.020	PN	MOS		N:0			27-DEC-2011		
	SN-UNKNOWN	HRS/MSC	13000	N:0			0		13000
AIRWORTHINESS	REF: AMM 52-30-07	AFL	17000	N:0			0		17000
52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
52.030		MOS	72	+6m/-6m	16		11-DEC-2017	31-DEC-2023	27-JUN-2024
		HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
	REF: See Workcard	AFL					1477		
52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM								
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF: AMM 52-70-00	AFL							
520005	PASSENGER DOOR								
52.050	5520512007	MOS		N:0			27-DEC-2011		
	1075P	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	5520512010	MOS		N:0			27-DEC-2011		
	1076P	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-30-01	AFL		N:0			0		
520015	EMERGENCY 6 SERIE EXIT								
52.060	5520512009	MOS		N:0			27-DEC-2011		
	5001	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-20-01	AFL		N:0			0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 53	FUSELAGE								
53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 18	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	300	+10%/-10%				2569.8	
	REF:	AFL							
53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 22	MOS	24	+10%/-10%				27-NOV-2019	
		HRS/MSC	2400	+10%/-10%				2569.8	
	REF:	AFL							
53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 22	MOS	24	+10%/-10%				27-NOV-2019	
		HRS/MSC	2400	+10%/-10%				2569.8	
	REF:	AFL							
53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 22	MOS	24	+10%/-10%				27-NOV-2019	
		HRS/MSC	2400	+10%/-10%				2569.8	
	REF:	AFL							
53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 21	MOS	12	+10%/-10%				27-NOV-2019	
		HRS/MSC	1200	+10%/-10%				2569.8	
	REF:	AFL							
53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)								
		MOS						27-DEC-2011	
		HRS/MSC	N/A					0	
AIRWORTHINESS	REF: GENERIC NO REF	AFL						0	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24 PKG 21	MOS	12	+10%/-10%			PKG	27-NOV-2019	
	REF: AMM 53-20-02	HRS/MSC	1200	+10%/-10%			2569.8		
		AFL							
53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION	MOS					27-DEC-2011		
53.100		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-10-06	AFL	42000				0	42000	
53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					27-DEC-2011		
53.110		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-10-00	AFL	42000				0	42000	
53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS	MOS					27-DEC-2011		
53.120		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-20-00	AFL	42000				0	42000	
53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43	MOS					27-DEC-2011		
53.130		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-30-00	AFL	42000				0	42000	
53-00/355	EXAMINE - ANTENNA STRUCTURE	MOS					27-DEC-2011		
53.140		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-00-00	AFL	42000				0	42000	
53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN	MOS					27-DEC-2011		
53.150		HRS/MSC	28300				0	28300	
AIRWORTHINESS	REF: AMM 53-00-00	AFL	37000				0	37000	
53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN	MOS					27-DEC-2011		
53.160		HRS/MSC	32500				0	32500	
AIRWORTHINESS	REF: AMM 53-00-00	AFL	42000				0	42000	



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION								
53.180		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION								
53.190		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-00-03	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION								
53.200		MOS					27-DEC-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210		MOS					27-DEC-2011		
AIRWORTHINESS	REF:	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
53-00/9	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE								
53.010		MOS					27-DEC-2011		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL	27000				0		27000
53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030		MOS	72	+6m/-6m	16		11-DEC-2017	31-DEC-2023	27-JUN-2024
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040		MOS	72	+6m/-6m	16		11-DEC-2017	31-DEC-2023	27-JUN-2024
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	72	+6m/-6m	16		11-DEC-2017	31-DEC-2023	27-JUN-2024
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	72	+6m/-6m			11-DEC-2017	31-DEC-2023	27-JUN-2024
	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	72	+6m/-6m			11-DEC-2017	31-DEC-2023	27-JUN-2024
	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
34.575		MOS	12	+1m/-1m			27-NOV-2019	30-NOV-2020	20-DEC-2020
	REF: AMM 53-30-01	HRS/MSC					2569.8		
		AFL							
530070	FUSELAGE AB 1003 TEIL1								
53.090	5530512114	MOS		N:0			27-DEC-2011		
	1075P	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 55 STABILIZERS									
55-00/10	STRUCTURAL LIMITATION TAIL STRUCTURE								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	20000				0	20000	
		AFL	27000				0	27000	
55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			2569.8		
		AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT PKG 21	MOS	12	+10%/-10%			PKG		
	REF: AMM 55-00-00	HRS/MSC	1200	+10%/-10%			27-NOV-2019		
		AFL					2569.8		
55-10/415	HORIZONTAL STABILIZER								
55.090	PN	MOS		N:0			27-DEC-2011		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
	REF: AMM 55-10-01	AFL	30000	N:0			0	30000	
55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	72	+6m/-6m		16	11-DEC-2017	31-DEC-2023	27-JUN-2024
	REF:	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	72	+6m/-6m		16	11-DEC-2017	31-DEC-2023	27-JUN-2024
	REF:	HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
		AFL					1477		
55-20/362	EXAMINE LEFT WING ELEVATOR								
55.100		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
+ 55-20/362	EXAMINE RIGHT WING ELEVATOR								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-20-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
55.110		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
55.120		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-20-01	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS.						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8		
	REF: GENERIC NO REF	AFL							
55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
		HRS/MSC	1200	+10%/-10%			2569.8		
	REF:	AFL							
55-30/369	EXAMINE - VERTICAL STABILIZER								
55.130		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-30-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE								
55.140		MOS					27-DEC-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER								
55.150		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-00-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT								
55.160		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-30-02	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40								
55.190		MOS					27-DEC-2011		
	REF:	HRS/MSC	32500				0		32500
		AFL	42000				0		42000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40/373	EXAMINE - RUDDER								
55.170		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-40-00	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
55.180		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 55-40-05	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200		MOS					27-DEC-2011		
	REF:	HRS/MSC	32500				0		32500
		AFL	42000				0		42000
CHAPTER 56 WINDOWS									
56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 18	MOS	12	+10%/-10%			27-NOV-2019		
	REF: AMM 56-00-00	HRS/MSC	300	+10%/-10%			2569.8		
		AFL							
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED								
56.020		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 56-20-01	HRS/MSC	A/R				0		
		AFL					0		
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED								
		MOS					27-DEC-2011		
	REF: AMM 56-00-00	HRS/MSC	A/R				0		
		AFL					0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)								
	9598110109	MOS					27-DEC-2011		
	10126H5664	HRS/MSC	A/R				0		
	REF:	AFL					0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED) 9598110110 10012H4086 REF: AMM 56-11-01	MOS HRS/MSC AFL	A/R				27-DEC-2011 0 0		
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110109 10126H5664 REF:	MOS HRS/MSC AFL	A/R				27-DEC-2011 0 0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION) 9598110110 10012H4086 REF:	MOS HRS/MSC AFL	A/R				27-DEC-2011 0 0		
56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS 56.100 REF: AMM 56-11-02	MOS HRS/MSC AFL	120 11000	+6m/-6m +500/-500			27-DEC-2011 0 0	31-DEC-2021 11000	27-JUN-2022 11500
56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED 56.110 AIRWORTHINESS REF: See Workcard	MOS HRS/MSC AFL	32500 42000				27-DEC-2011 0 0	32500 42000	
56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS PKG 18 REF: AMM 56-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
560015	SIDE,LH WINDOW 56.090 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560020	SIDE,RH WINDOW								
56.090	9598110112 09194H5421 REF: AMM 56-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560025	RH NO 1 CABIN WINDOW								
56.060	5562012029 684061-008 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560030	RH NO 2 CABIN WINDOW								
56.060	5562012029 10650 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560035	RH NO 3 CABIN WINDOW								
56.070	5562012029 10670 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560040	RH NO 4 CABIN WINDOW								
56.070	5562012029 684061-011 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560045	RH NO 5 CABIN WINDOW								
56.080	5562012029 684061-007 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560050	LH NO 1 CABIN WINDOW								
56.040	5562012029 10671 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560055	LH NO 2 CABIN WINDOW								
56.040	5562012029 10648 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560060	LH NO 3 CABIN WINDOW								
56.050	5562012029 10649 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560065	LH NO 4 CABIN WINDOW								
56.050	5562012029 10691 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
560070	DV-WINDOW ASSY								
56.030	5561412099 1028H3854 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
561010	LEFT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	9598110109 10126H5664 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
561011	RIGHT HAND WINDSHIELD ASSY, (LH)								
56.010 AIRWORTHINESS	9598110110 10012H4086 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
CHAPTER 57 WINGS									
57-00/11	STRUCTURAL LIMITATION LEFT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: AMM 57-00-00	MOS HRS/MSC AFL	20000 27000				27-DEC-2011 0 0	20000 27000	
57-00/11	STRUCTURAL LIMITATION RIGHT WING STRUCTURE								
57.010 AIRWORTHINESS	REF: AMM 57-00-00	MOS HRS/MSC AFL	20000 27000				27-DEC-2011 0 0	20000 27000	



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES PKG 18	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	300	+10%/-10%					
57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS PKG 22	MOS	24	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	2400	+10%/-10%					
57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS					27-DEC-2011		
AIRWORTHINESS	REF:	HRS/MSC AFL	N/A				0 0		
57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS					27-DEC-2011		
AIRWORTHINESS	REF:	HRS/MSC AFL	N/A				0 0		
57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS					27-DEC-2011		
57.100		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0		39000
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS					27-DEC-2011		
		HRS/MSC	30000				0		30000
AIRWORTHINESS	REF: AMM 57-00-00	AFL	39000				0		39000



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION								
57.110		MOS					27-DEC-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC	30000				0		30000
		AFL	39000				0		39000
57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT								
57.120		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
57.130		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
57.140		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-20-05	HRS/MSC	25000				0		25000
		AFL	30000				0		30000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					27-DEC-2011		
57.150		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3	MOS					27-DEC-2011		
		HRS/MSC	25000				0	25000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	30000				0	30000	
57-00/412	EXAMINE - WING TIPS	MOS					27-DEC-2011		
57.170		HRS/MSC	32500				0	32500	
	REF:	AFL	42000				0	42000	
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES	MOS					27-DEC-2011		
		HRS/MSC	25000	+500/-500			0	25000	25500
	REF: AMM 57-20-01	AFL	30000	+500/-500			0	30000	30500
57-00/413	EDDY CURRENT INSPECTION - WING SKIN AROUND DRAIN HOLES	MOS					27-DEC-2011		
57.180		HRS/MSC	25000				0	25000	
	REF:	AFL	30000				0	30000	
57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					27-DEC-2011		
		HRS/MSC	16000				0	16000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0	22500	
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6	MOS					27-DEC-2011		
		HRS/MSC	16000				0	16000	
AIRWORTHINESS	REF: AMM 57-20-10	AFL	22500				0	22500	
57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)	MOS	72	+6m/-6m	16		11-DEC-2017	31-DEC-2023	27-JUN-2024
57.020		HRS/MSC	6000	+500/-500			2027.02	8027.02	8527.02
	REF: GENERIC NO REF	AFL					1477		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	72	+6m/-6m			11-DEC-2017	31-DEC-2023	27-JUN-2024
	REF: GENERIC NO REF	HRS/MSC	6000	+500/-500	16		2027.02	8027.02	8527.02
		AFL					1477		
57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040		MOS	120	+6m/-6m			27-DEC-2011	31-DEC-2021	27-JUN-2022
	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			0	11000	11500
		AFL					0		
+ 57-60/393	EXAMINE - RIGHT WING AILERON								
		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/393	EXAMINE -LEFT WING AILERON								
57.160		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 57-60-00	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
57-60/411	EXAMINE - AILERON TRIM TAB								
57.190		MOS					27-DEC-2011		
	REF:	HRS/MSC	32500				0	32500	
		AFL	42000				0	42000	
570005	AILERON LH 10A SERIE ASSY								
57.050	5570512017	MOS		N:0			27-DEC-2011		
	3075P	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570010	AILERON RH 10A SERIE ASSY								
57.050	5570512018	MOS		N:0			27-DEC-2011		
	3075P	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-60-02	AFL		N:0			0		
570050	L/H WING								
57.080	5570512137	MOS		N:0			27-DEC-2011		
	1075P	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570055	R/H WING								
57.090	5570512138 1075P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 61 PROPELLERS/PROPULSORS

61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 21	MOS	12	+10%/-10%			27-NOV-2019		
	REF:	HRS/MSC	1200	+10%/-10%			2569.8		
		AFL							
61PR1	NO. 1 PROPELLER								
61.PR1	968291303 KX958 REF: See Workcard	MOS HRS/MSC AFL	PP/C						

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01

612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	3049558-01	MOS		N:0			27-DEC-2011		
	17124075	HRS/MSC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL	REF: EMM 61-20-00	ENC		N:0			0		
612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
	3037685	MOS		N:0			27-DEC-2011		
	17104487	HRS/MSC	3500	+500	N:0		0	(3500) 3500	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		

PROPELLER NO. 1 Model : HC-E4A-3 Serial # KX958 Part # 968291303

+ 610010	NO. 1 PROPELLER - OVERHAUL								
		MOS	72				11-DEC-2017	31-DEC-2023	
		HRS/MSC	4000				2027.02	(6027.02) 6027.02	
OVERHAUL	REF: POM 61-00-49								
610020	NO. 1 PROPELLER - ACCOMPLISH A DETAILED INSPECTION								
		MOS	12		-8		27-NOV-2019	30-NOV-2020	
		HRS/MSC	400				2569.8	(2969.8) 2969.8	
	REF: POM 61-00-49								

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
610030	NO. 1 PROPELLER - LUBRICATE PROPELLER REF: POM 61-00-49	MOS HRS/MSC	12 400			-8	27-NOV-2019 2569.8	30-NOV-2020 (2969.8) 2969.8	
611501	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE 9682913023 L06385 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			27-DEC-2011 0		
611502	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE 9682913023 L06383 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			27-DEC-2011 0		
611503	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE 9682913023 L06386 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			27-DEC-2011 0		
611504	NO. 1 PROPELLER - NO. 4 PROPELLER BLADE 9682913023 L06384 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			27-DEC-2011 0		

CHAPTER 71		POWER PLANT							
71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER							PKG	
71.010	PKG 20 REF: See Workcard	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE							PKG	
	PKG 20 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/103	PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH								
71.040	REF: AMM 71-00-00	MOS HRS/MSC AFL	12 300				27-NOV-2019 2569.8	30-NOV-2020 2869.8	
71-00/104	PERFORM COMPRESSOR DESALINATION WASH								
	REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				06-APR-2018 2123.4 1545		
71-00/105	PERFORM TURBINE WASH								
	REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				14-NOV-2018 2316.7 1678		
71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 20 REF: AMM 71-00-03	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN SN-UNKNOWN REF: AMM 71-00-05	MOS HRS/MSC AFL	20000 27000		N:0 N:0 N:0		27-DEC-2011 0 0	20000 27000	
AIRWORTHINESS									
71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	11000				27-DEC-2011 0 0	11000	
AIRWORTHINESS									
71-00/204 (s)	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 16 ,17,18,19,20,21,22 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				27-NOV-2019 2569.8		
71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP						PKG		
	PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES. REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION AND DO THE 100 HOUR AND MINOR INSPECTION ITEMS PKG 16 ,17,18,19,20,21,22 REF:	MOS HRS/MSC AFL	A/R				27-NOV-2019 2569.8		
71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
71-00/287 (s)	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS. PKG 16 ,17,18,19,20,21,22 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				27-NOV-2019 2569.8		
71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. PKG 22 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 5654 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		27-DEC-2011 0 0	3500	3850
71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 5675 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		27-DEC-2011 0 0	3500	3850
71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 5671 REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		27-DEC-2011 0 0	3500	3850

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	944.81.21.409	MOS		N:0			27-DEC-2011		
OVERHAUL	5667	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	944.81.21.409	MOS		N:0			27-DEC-2011		
OVERHAUL	5673	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
71.130		MOS					27-DEC-2011		
AIRWORTHINESS	REF: AMM 71-00-05	HRS/MSC	26600				0	26600	
		AFL	35000				0	35000	
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
	REF:	HRS/MSC	A/R				2569.8		
		AFL							
71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
	REF:	HRS/MSC	A/R				2569.8		
		AFL							
71-10/208 (s)	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR						PKG		
	PKG 16 ,17,18,19,20,21,22	MOS					27-NOV-2019		
	REF:	HRS/MSC	A/R				2569.8		
		AFL							
710050	(WELDED) ENGINE MOUNT								
71.120	5712012036	MOS		N:0			27-DEC-2011		
	1098	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-00-05	AFL		N:0			0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P	MOS							
	PCE-RY0296	HRS/MSC	E/C						
	REF: AMM 71-00-00	AFL							



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									
710011	NO. 1 ENGINE - OVERHAUL	MOS					27-DEC-2011		
OVERHAUL	REF: GENERIC NO REF	HRS/MSC	3500	+200			0	(3500) 3500	3700
		ENC					0		
710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE	MOS					06-APR-2018		
	REF: EMM 72-30-05	HRS/MSC	300	+10%/-10%			2123.4		
		ENC					1545		
710021	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					06-DEC-2016		
	REF: EMM 72-00-00	HRS/MSC	1750	+250	-21.2		1771.2	(3500) 3500	3750
		ENC					1303		
710031	NO. 1 ENGINE - BORESCOPE HOT SECTION	MOS					27-NOV-2019		
	REF: EMM 72-00-00	HRS/MSC	300	+10%/-10%			2569.8	(2869.8) 2869.8	2899.8
		ENC							
710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES	MOS					27-DEC-2011		
	REF: EMM 72-00-00	HRS/MSC	4000	+100/-100			0	(4000) 4000	4100
		ENC					0		
710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION	DAYS					06-APR-2018		
	REF: See Workcard	HRS/MSC	A/R				2123.4		
		ENC					1545		
710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM)	MOS					22-FEB-2013		
	REF: EMM 72-00-00	HRS/MSC	A/R				537.8		
		ENC					417		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE	MOS					27-DEC-2011		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									
720010	NO. 1 ENGINE - GAS GENERATOR MODULE	MOS					27-DEC-2011		
	PN	HRS/MSC	3500	+500			0	(3500) 3500	4000
OVERHAUL	REF: See Workcard	ENC					0		
720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL	MOS					(EBT)		
	REF: EMM 72-00-00	HRS/MSC BF/F							
		ENC							
720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP	MOS					(EBT)		
	REF: EMM 72-60-00	HRS/MSC BF/F							
		ENC							
721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS					(EBT)		
	REF: EMM 72-11-00	HRS/MSC BF/F							
		ENC							
723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR	MOS					27-DEC-2011		
	3042701	HRS/MSC					0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000				0	(24000) 24000	
723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT	MOS					27-DEC-2011		
	3043063	HRS/MSC					0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000				0	(24000) 24000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 EAAC000D835	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR 3040933 EAAC000D420	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR 3040944 EAAC000D192	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3036898 EAAC000D935	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000	N:0			0	(24000) 24000	
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION REF: See Workcard	MOS HRS/MSC ENC	A/R				27-DEC-2011 0 0		
	UNSCHEDULED MAINTENANCE CHECK								
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK 3053740-01 A002WL8H	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	N:0			0	(8000) 8000	
725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000				27-DEC-2011 0 0	(5000) 5000	
725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312 A002R05M	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 15000	

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313 YUAA007A003	MOS HRS/MSC		N:0 N:0			27-DEC-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 15000	
725050	NO. 1 ENGINE - NO. 1 COMPRESSOR TURBINE BLADE 3118911-01 SN-UNKNOWN	MOS HRS/MSC	O/C				30-NOV-2016 1771.2		
	REF: GENERIC NO REF	ENC					1303		
726020	NO. 1 ENGINE - POWER SECTION MODULE PN SN-UNKNOWN	MOS HRS/MSC	3500	N:0 N:0	+500		27-DEC-2011 0	(3500) 3500	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									
731010	NO. 1 ENGINE - FUEL PUMP 3040760 010660	MOS HRS/MSC	3500	N:0 N:0			27-DEC-2011 0	(3500) 3500	
OVERHAUL	REF: EMM 73-10-02	ENC		N:0			0		
731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS HRS/MSC	600		+10%/-10%		20-NOV-2018 2316.7	(2916.7) 2916.7	2976.7
	REF: See Workcard	ENC					1678		
731030	NO. 1 ENGINE - OVERTORQUE LIMITER 3055748-01 C51171	MOS HRS/MSC	3500	N:0 N:0	+500		27-DEC-2011 0	(3500) 3500	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		
731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION	MOS HRS/MSC	N/A				27-DEC-2011 0		
	REF: EMM 73-10-02	ENC					0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 010660 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			27-NOV-2019 2569.8 1851	(3169.8) 3169.8	3229.8
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 010660 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				06-APR-2018 2123.4 1545		
731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	1800	+100/-100		75.7	01-SEP-2016 1724.3 1277	(3600) 3600	3700
731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER 572744 SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			27-NOV-2019 2569.8	(3169.8) 3169.8	3229.8
731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA40522 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-DEC-2011 0 0	(3500) 3500	4000
731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-DEC-2011 0 0	(3500) 3500	4000
731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-07 17165421 REF: EMM 73-20-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		27-DEC-2011 0 0	(3500) 3500	4000

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	4000	N:0 N:0 N:0			27-DEC-2011 0 0	(4000) 4000	
731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			27-NOV-2019 2569.8 1851	(2869.8) 2869.8	2899.8
731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER 572744 SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T	N:0 N:0 N:0			27-NOV-2019 2569.8		
732010	NO. 1 ENGINE - FUEL FLOW TRANSMITTER TFF1573-20 AAC3445AM REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				11-APR-2015 1306.8 998		
733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%	20.9		01-SEP-2017 1963.7 1437	(2884.6) 2884.6	2974.6
733070 (s)	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY PKG 0 REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			PKG 27-NOV-2019 2569.8		
CHAPTER 74	IGNITION								
74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 18 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA10390036 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500			27-DEC-2011 0 0	(3500) 3500	4000
740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%			27-NOV-2019 2569.8 1851	(2969.8) 2969.8	3009.8
740020	NO. 1 ENGINE - 4 O'CLOCK IGNITER PLUG CH34055 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				20-NOV-2018 2316.7 1678		
740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			27-NOV-2019 2569.8 1851	(2969.8) 2969.8	3009.8
740040	NO. 1 ENGINE - 9 O'CLOCK IGNITER PLUG CH34055 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				20-NOV-2018 2316.7 1678		

CHAPTER 75

AIR

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01

750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX017325 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500			27-DEC-2011 0 0	(3500) 3500	4000
--------	---	-----------------------	------	------	--	--	-----------------------	-------------	------

CHAPTER 76

ENGINE CONTROLS

76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 20 REF:	MOS HRS/MSC AFL	12	+10%/-10%			27-NOV-2019 2569.8		
---------------	---	-----------------------	----	-----------	--	--	-----------------------	--	--

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 17 REF: AMM 76-10-00	MOS HRS/MSC AFL	300	+10%/-10%			PKG 27-NOV-2019 2569.8		
76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 21 REF: See Workcard	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 18 REF:	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 27-NOV-2019 2569.8		
76-10/117 76.010	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES REF: AMM 76-10-02	MOS HRS/MSC AFL	12 3000	+10%/-10% +10%/-10%	-8		27-NOV-2019 2569.8	30-NOV-2020 5569.8	25-DEC-2020 5869.8
760015 76.020	MANUAL OVERRIDE CABLE ASSY. 9419411417 20100937 REF: AMM 76-20-00	MOS HRS/MSC AFL	O/C				27-DEC-2011 0 0		
760020 76.030	CONDITION CABLE ASSY. 9419411418 20101028 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760025	POWER CONTROL CABLE ASSY.								
76.040	9419411419 20101021 REF: AMM 76-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 77 ENGINE INDICATING

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
77.010	9752115206 7765-7-33 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
770010	DIFFERENTIAL PRESSURE,PDCR130/35WL/C TRANSDUCER								
77.030	9752115212 3137415 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01

7701PA	NO. 1 ENGINE - PERFORM ENGINE TREND MONITORING (NON GROUNDING)								
CUSTOMER CODE	REF:	DAYS HRS/MSC ENC	30				29-APR-2020	29-MAY-2020	
771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01 NR05380 REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		

CHAPTER 78 EXHAUST

78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 18	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			27-NOV-2019 2569.8		
78-CUS-01	LH EXHAUST STACK								
	578.10.12.045 182057 REF:	MOS HRS/MSC AFL	O/C				20-NOV-2018 2318.3 1681		

CHAPTER 79 OIL

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK PKG 20	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: See Workcard	HRS/MSC AFL	600	+10%/-10%					
79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT PKG 21	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF:	HRS/MSC AFL	1200	+10%/-10%					
79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 18	MOS	12	+10%/-10%			PKG 27-NOV-2019 2569.8		
	REF: AMM 79-30-01	HRS/MSC AFL	300	+10%/-10%					
79-20/43	OIL COOLER 9683214102	MOS		N:0			27-DEC-2011		
79.010	T1202	HRS/MSC	3500	+10%/-10%			0	3500	3850
OVERHAUL	REF: AMM 79-20-02	AFL		N:0			0		
790005	TEMPERATURE BULB 9751120101	MOS		N:0			27-DEC-2011		
79.020	157122	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
790020	PRESSURE,GAGE SWITCH 973.81.14.307	MOS					26-NOV-2014		
79.030	0784	HRS/MSC	O/C				1159.5		
	REF: AMM 79-30-04	AFL					897		
790020-6	SWITCH,PRESSURE,GAGE 9738114305	MOS		N:0			31-MAY-2011		
	1139	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		
790025	THERMAL ACTUATOR 9787301002	MOS		N:0			27-DEC-2011		
79.040	1309	HRS/MSC	O/C	N:0			0		
	REF: AMM 79-20-02	AFL		N:0			0		

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0296 Part # 3072955-01									
790021	NO. 1 ENGINE - SERVICING OF OIL SYSTEM	MOS					27-DEC-2011		
DISCARD	REF: GENERIC NO REF	HRS/MSC A/R					0		
		ENC					0		
790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			27-NOV-2019	30-NOV-2020	27-DEC-2020
		HRS/MSC	300	+10%/-10%			2569.8	(2869.8) 2869.8	2899.8
	REF: EMM 79-20-02	ENC					1851		
790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS	12	+1m/-1m	9		27-NOV-2019	31-DEC-2020	06-JAN-2021
		HRS/MSC	600	+10%/-10%			2569.8	(3169.8) 3169.8	3229.8
	REF: EMM 79-20-02	ENC					1851		
790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS					01-SEP-2017		
		HRS/MSC	900	+10%/-10%	20.9		1963.7	(2884.6) 2884.6	2974.6
	REF: EMM 79-20-02	ENC					1437		
790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN	MOS					27-NOV-2019		
		HRS/MSC	300	+10%/-10%			2569.8	(2869.8) 2869.8	2899.8
	REF: EMM 79-20-02	ENC							
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					01-SEP-2017		
		HRS/MSC	1000	+10%/-10%	20.9		1963.7	(2984.6) 2984.6	3084.6
	REF: EMM 72-60-00	ENC					1437		
790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					27-NOV-2019		
		HRS/MSC	150	+10%/-10%			2569.8	(2719.8) 2719.8	2734.8
	REF: EMM 79-20-02	ENC					1851		
CHAPTER 80 STARTING									

Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
801010	NO. 1 GENERATOR								
80.005	9789123437 P1620 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
801015	NO. 2 STARTER GENERATOR								
80.010	9789123437 P1591 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:21 N:749.2 N:574			12-SEP-2013 749.2 574		
CHAPTER 91 -									
910015	KBT 300 TTP BUS RES, A-157 TERMINAL								
90.015	9859912117 KBT300-2250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL								
90.025	9859912117 KBT300-2224 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL								
90.020	9859912117 KBT300-2227 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
910030	PILOT LEFT HD POWER, FE1549L JUNCTION BOX								
90.030	9740338136 449 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		
910035	CO-PILOT RIGHT HD POWER, FE1549R JUNCTION BOX								
90.030	9740338143 431 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-DEC-2011 0 0		



Status Report

PC-12/47E S/N 1286 (N286NW): 2654.9 HRS, 1902 AFL as of 07-Apr-2020

Owner/Operator: PRIESTER AVIATION, LLC

Report Date: 05-MAY-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
	9859912117	MOS		N:0			27-DEC-2011		
90.010	KBT300-2256	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
91C097	BATT/ EXT PWR (BEPJB) JUNCTION BOX								
	9740338142	MOS		N:0			31-MAY-2011		
	510	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		